

PT-E2500 Series

Software release notes v.2.03.15



About This Document

This document provides a general description of the release and its new features. It also describes additions or changes, resolved issues, and any relevant open issues by the release.



version	V2.03.15
date	2016-08-12

item	The description of the release and its new features	
1	Adapt the wrong version number for E613 ONU	

version	V2.03.15
date	2016-08-9

item	The description of the release and its new features	
1	Improve the onu response when a onu return a value	
	0x0,change it to 0x86,it means that the attribute or the	
	action is invalid.	
2	Add user management in web	



version	V2.03.14
date	2016-08-01

item	The description of the release and its new features	
1	Change the time of the onu bandwidth assignment, when a	
	onu is authenticated, the olt will assign the bandwidth for it	
2	Improve the oam communication mechanism	

version	V2.03.13
date	2016-07-28

item	The description of the release and its new features	
1	Add web management	
2	Add update the onu firmware automatically	
3	Fix olt oam process when onu responses a wrong oam	
4	Fix a bug for saveing default user password issue	



version	V2.03.12
date	2016-05-11

item	The description of the release and its new features Fixed a bug for onu mac authentication	
1		

version	V2.03.11
date	2016-04-29

item	The description of the release and its new features	
1	Add a state for ems system when a onu finished it's register	
2	Fixed a CLI login bug for character '!', you can go into config	
	mode when you input the character '!'	

version	V2.03.10
date	2016-04-15

item	The description of the release and its new features
------	---



PT-E2500 Series v.2.03.15

1	improve onu register process because this problem will
	cause the OLT does not respond to onu

version	V2.03.09
date	2016-03-29

item	The description of the release and its new features
1	Fixed a bug for deleting a onu operation, the onu can not
	register if do not reboot the olt
2	Add a command to show all onu's receive power in a pon
3	the acl rule can be used in Multiple ports

version	V2.03.08
date	2016-03-23

item	The description of the release and its new features
------	---



1	Fixed some operations for ems management
2	Add olt serial number and mac authentication

version	V2.03.07
date	2016-03-01

item	The description of the release and its new features	
1	Add ONU communication for the same pon port	

version	V2.03.06
date	2016-02-26

item	The description of the release and its new features
1	Add private oam for CATV, WIFI management
2	Add DHCP Server, DHCP Relay, DHCP SNOOPING

version	V2.03.05
date	2016-01-13



item	The description of the release and its new features
1	Change I2ftp timeout from 15s to 30s to avoid re-sending
	image block

version	V2.03.04
date	2016-01-4

item	The description of the release and its new features
1	Disable automatic conntrack

version	V2.03.03
date	2015-12-30

item	The description of the release and its new features
1	Fix some issues for EMS service profile configuration

version	V2.03.01



PT-E2500 Series v.2.03.15

date	2015-12-21

item	The description of the release and its new features
1	Add OLT type hardware identification,so 2/4/8 port OLTs
	will use the same firmware

version	V1.03.49
date	2015-12-14

item	The description of the release and its new features
1	Fix a issue for HG323UE register link lose
2	Use olt type string to identify what type of olt the olt is
3	

version	V1.03.45
date	2015-11-30

item	The description of the release and its new features
1	Change aux port bandwidth from 5M to 10M



2	Fix a issue for default onu type, it cann't identify the known
	onu types
3	Cancel the aux brandwidth limit for aux download issue

version	V1.03.43
date	2015-11-25

item	The description of the release and its new features
1	Fixed a upload configure file to tftp server issue
2	Improve the ctc extend oam discovery process
3	Add default onu type for 1GE,4GE,4FE,8FE

version	V1.03.42
date	2015-11-12

item	The description of the release and its new features
1	Fixed a onu port issue for snmp process
2	Fixed a onu multicast vlan strip issue for snmp process
3	Add a re-transmission mechanism during the period of onu
	discovery



version	V1.03.41
date	2015-11-3

item	The description of the release and its new features
1	Add the function to check the vlan ip address with the aux
	interface's address whether or not the same
2	Save the ip route 0.0.0.0/0 configuration
3	Add the gateway for aux interface
4	Delete a port by switchport hybrid vlan 1 untagged,
	Then save and reboot, the port will not has switchport
	hybrid vlan 1 untagged configuration